


ENTRANCE THRU TURTLE RIVER

EAST RIVER

S BRUNSWICK

* AREA IS BEING DREDGED
 ** AREA TO BE DREDGED

NOTE:
 1. THE INFORMATION CONTAINED ON THIS SHEET REPRESENTS THE DATA FOR THE CHANNEL AND IS NOT A GUARANTEE OF THE CHANNEL CONDITIONS EXISTING AT THE TIME.
 2. THESE PROFILES ARE FOR INFORMATION PURPOSES ONLY AND DO NOT REPRESENT A GUARANTEE OF CHANNEL DEPTH. THE USER SHOULD CONSULT THE APPROPRIATE AGENCIES AND THE U.S. NAVY FOR THE LATEST INFORMATION ON THE CHANNEL DEPTHS AND CONDITIONS.



U.S. NAVY ENGINEERING DISTRICT OFFICE
 OFFICE OF HYDROGRAPHY

BRUNSWICK HARBOR, GEORGIA
 BRUNSWICK HARBOR PROFILES

BRUNSWICK GEORGIA

DATE: 10/13/18 DRAWING NO.: DBB-103/318

SCALE: AS SHOWN SHEET 3 OF 3